



MPA
Industrie
Service



CERTIFICATE OF ATTESTATION

Inspection Number: MPA/41/18/2568	Scope of inspection: KÖŞKERLER ÇELİK HALAT VE MAKİNA SANAYİ ANONİM ŞİRKETİ technical documents inspection of 2006/42/EC (ex 98/37/EEC) Machinery Directive and 73/361/EC for STELL WIRE ROPES
Inspection ordered to MPA by: KÖŞKERLER ÇELİK HALAT VE MAKİNA SANAYİ ANONİM ŞİRKETİ Çerkeşli Köyü OSB Mahallesi İMES Bulvarı No:20 İMES Organize Sanayi Bölgesi DİLOVASI / KOCAELİ / TÜRKİYE	
Subject of inspection: Document inspection of 2006/42/EC (ex98/37/EEC) Machinery Directive and 73/361/EC marking of wire-ropes, chains and hooks for STELL WIRE ROPES (1*7, 1*19, 6*7, 8*7, 6*19, 8*19, 6*25, 6*36)	
Scope of the inspection: Document inspection of preparing technical files, reviewing test reports, component certification compability, application and settlement of CE marking directives rules	
This supply complies with the following applicable documents: MACHINERY DIRECTIVE 2006/42/EC (ex 98/37/EEC) MARKING OF WIRE-ROPES, CHAINS AND HOOKS DIRECTIVE 73/361/EEC EN 12385 - 4 / EN 12385-5	
Marking and logos on the items: CE Marking Comments or/and particulars: The undersigned report that is above mentioned supply was inspected in document conformity with according to scope.	
Date of issued: 21.11.2016	Inspector
Validated by 	
Location of inspection: Customer area.	
This report, based on the contract signed between the producer and our body, has been issued on the voluntary field. While displaying the results obtained from the technical documents submitted to our body by the producer, this report nohow guarantees the product and production process. This report is valid only for the technical documents of product.	

ΠΙΣΤΟΠΟΙΗΤΙΚΟ - CERTİFİKA - İGAZOLÁS - INTYG - Vottorò - ԾԻՌՈՒՄ - SIJIL - POTRDILO - سرٹیفکیٹ

RTIFICATE - ZERTIFIKAT - CERTIFICATO - CERTIFICADO - ҮҢІТҢ ҚА - CERTIFIKAT - 證書 - گواهی